















Праліне/Praline



Комод 2Д4Ш / Chest of drawers 2D4Dr








 (A1) 8*30mm x16	 (B) ϕ 12mm x28	 (B1) 6,3*50mm x28
 (C1) 6*43mm x24	 (D) ϕ 20mm x24	 (D1) 15/15 x24
 (E4) 3*15mm x12	 (E6) 3,5*16mm x76	 (F4) 6,3*13mm x8
 (H2) RV-8 x33	 (I33) L- 128mm x6	 (J1) 5*16mm x16
 (K38) h-120mm x5	 (L17) x4	 (L19) x4
 (M14) L- 350mm x4	 (O8) L- 577/378mm x1/x2	

No	a*b	x	N°→...
1/1	814x400	x1	1/3
1/2	814x400	x1	1/3
2/1	754x386	x1	2/3
2/2	754x386	x1	2/3
3	1368x384	x1	2/3
4	1400x400	x1	2/3
5	60x1368	x1	2/3
6	378x368	x4	3/3
7	748x373	x2	3/3
8	185x572	x4	2/3
9/1	350x150	x4	1/3
9/2	350x150	x4	1/3
10	519x150	x4	1/3
11	528x343	x4	2/3
12	378x1377	x2	2/3
		x1	1/3











x4




 A1 8*30mm x4	 C1 6*43mm x4	 F4 6,3*13mm x8
 L17 x4		


1






 A1 8*30mm x8	 D1 15/15 x4	 E6 3,5*16mm x16
 M14 L- 350mm x4		


2




 A1 8*30mm x4	 C1 6*43mm x4	 D1 15/15 x4
---	---	--

3





 (E6) 3,5*16mm x8	 (L19) x4
--	--

4






5




 (B) $\varnothing 12\text{mm}$ x4	 (B1) 6,3*50mm x4
---	---


6





7








8







 (B) $\phi 12\text{mm}$ x8	 (B1) 6,3*50mm x8
--	---


10




 (E6) 3,5*16mm x20	 (H2) RV-8 x9	 (K38) h-120mm x5
---	--	--


11



 D $\phi 20\text{mm}$ x8	 J1 5*16mm x16
---	--

12







 (B) $\varnothing 12\text{mm}$ x16	 (B1) 6,3*50mm x16	 (D1) 15/15 x16
--	--	---

13

13.1


x4








13


13.2
x4




13.3
x4




13


 (D) $\phi 20\text{mm}$ x16	 (H2) RV-8 x24
---	--

13.4
x4




13.5
x4




 (E4) 3*15mm x8	 (E6) 3,5*16mm x16	 (I33) L- 128mm x4
 (M14) L- 350 x4		

13




13.6 x4




13.7 x4






14



15

 (E4) 3*15mm x4	 (I33) L- 128mm x2
---	--



16

