
















Еліо/Elio


Шафа 1Д1Ш **Wardrobe 1D1Dr**







 (A1) 8*30mm x36	 (B) $\phi 12\text{mm}$ x4	 (B1) 6,3*50mm x4
 (C1) 6*43mm x40	 (D) $\phi 20\text{mm}$ x40	 (D1) 15/15 x40
 (E4) 3*15mm x4	 (E6) 3,5*16mm x16	 (H2) RV-8 x18
 (I64) 06R/0096 CSH x2	 (J5) x8	 (K16) $\phi 50 * h27\text{mm}$ x4
 (L23) x4	 (M2) L-300 mm x1	 (O8) L- 1515mm x1
 (T10) L-1516mm x1	 (T20) L-1516mm x1	 (T21) x1
 (T24) x1	 (U3) x2	

No	a*b	x	N°→...
1/1	1600x400x16	1	2/2
1/2	1600x400x16	1	2/2
2	1516x342x16	1	2/2
3	618x356x16	1	1/2
4	618x356x16	1	1/2
5	221x342x16	4	1/2
6	381x342x16	2	1/2
7	380x332x16	2	1/2
8	1350x397x16	1	2/2
9	192x397x16	1	2/2
10/1	300x130x16	1	1/2
10/2	300x130x16	1	1/2
11	323x130x16	1	1/2
12	332x293x3	1	1/2
13	1525x312x3	2	2/2
		1	1/2




 (C1) 6*43mm x20	 (E6) 3,5*16mm x2	 (M2) L-300 mm x1
--	---	---




1




 (A1) 8*30mm x4	 (D1) 15/15 x4	 (E6) 3,5*16mm x2
 (M2) L-300 mm x1		


2




 (C1) 6*43mm x8	 (T10) L-1516mm x1	 (T20) L-1516mm x1
--	---	---

3





 A1 8*30mm x8	 C1 6*43mm x4	 D1 15/15 x8
---	---	--


4




 A1 8*30mm x24	 D1 15/15 x24
---	--

5




 (E6) 3,5*16mm x8	 (L23) x4
---	---




6




7




8




9




10




11






12







13




 (H2) RV-8 x14	 (K16) $\varnothing 50 \times h27\text{mm}$ x4
--	---


14



 D $\phi 20\text{mm}$ x32	 J5 x8
---	---




15




 (B) $\varnothing 12\text{mm}$ x4	 (B1) 6,3*50mm x4	 (D1) 15/15 x4
--	---	--

16


16.1 x1








16

16.2
x1




16.3
x1




16



 (D) $\phi 20\text{mm}$ x4	 (H2) RV-8 x4
--	---

16.4
x1




16.5
x1




 (E4) 3*15mm x2	 (E6) 3,5*16mm x4	 (I64) 06R/0096 CSH x1
 (M2) L- 300 x1		

16




16.6
x1




16.7
x1




17









 E4 3*15mm x2	 I64 06R/0096 CSH x1	 U3 x2
--	---	---

18



19



20

