














Праліне/Praline


Тумба 2Д2Ш/ Cabinet 2D2Dr








 A1 8*30mm x20	 B ϕ 12mm x19	 B1 6,3*50mm x19
 C1 6*43mm x22	 D ϕ 20mm x22	 D1 15/15 x22
 E4 3*15mm x8	 E5 3*20mm x5	 E6 3,5*16mm x52
 F4 6,3*13mm x8	 H2 RV-8 x18	 I33 L- 128mm x4
 J1 5*16mm x12	 K38 h-120mm x5	 L17 x4
 L19 x4	 M14 L- 350mm x2	 O1 x5



No	a*b	x	N°→...
1/1	1084x400	x1	2/2
1/2	1084x400	x1	2/2
2	1024x386	x1	2/2
3	768x384	x1	1/2
4	800x400	x1	2/2
5	376x386	x2	5/2
6	375x368	x3	1/2
7	60x768	x1	1/2
8	617x370	x1	1/2
9	834x370	x1	1/2
10	188x370	x2	1/2
11/1	350x150	x2	1/2
11/2	350x150	x2	1/2
12	317x150	x2	2/2
13	326x343	x2	1/2
14	1029x388	x2	2/2
		x1	1/2




 A1 8*30mm x2	 C1 6*43mm x4	 F4 6,3*13mm x4
 L17 x2		




1




 A1 8*30mm x2	 C1 6*43mm x4	 E6 3,5*16mm x4
 F4 6,3*13mm x4	 L17 x2	 M14 L- 350mm x1



2





 A1 8*30mm x4	 C1 6*43mm x2	 D1 15/15 x2
 E6 3,5*16mm x4	 M14 L- 350mm x1	

3










5




6




7




8




 B $\phi 12\text{mm}$ x4	 B1 6,3*50mm x4
---	---


9






10




11











12




 B $\phi 12\text{mm}$ x6	 B1 6,3*50mm x6
---	---


13




 (E5) 3*20mm x5	 (E6) 3,5*16mm x20	 (H2) RV-8 x10
 (K38) h-120mm x5	 (O1) x5	


14



 (D) $\phi 20\text{mm}$ x14	 (J1) 5*16mm x12
--	--



15



 (B) $\varnothing 12\text{mm}$ x8	 (B1) 6,3*50mm x8	 (D1) 15/15 x8
---	---	--



16

16.1 x2






16


16.2
x2




16.3
x2




16


 (D) $\phi 20\text{mm}$ x8	 (H2) RV-8 x8
--	---

16.4
x2




16.5
x2




 (E4) 3*15mm x4	 (E6) 3,5*16mm x8	 (I33) L- 128mm x2
 (M14) L- 350 x2		

16



16.6
x2




16.7
x2






17



18

 (E4) 3*15mm x4	 (I33) L- 128mm x2
---	--



19

