












Спейс / Space


**шафа з кутовим закінченням (2200) /
corner cabinet (2200)**









 (C1) 6*43mm x55	 (D) $\phi 20$ mm x55	 (D1) 15/15 x55
 (E3) 3*13mm x4	 (E6) 3,5*16mm x8	 (2E) 4,2*16mm x2
 (F4) 6,3*13mm x8	 (G5) M 4*20mm x6	 (K16) $\phi 50$ *h27mm x4
 (L1) x2	 (L24) x2	 (P4) L-564mm x1
 (P5) x2	 (O8) L-2141 mm x1	 (R3) 1.4*25mm 30g
 (S16) 260.54.900 x1	 (U3) x2	


L




№	a*b	x	№→...
1	2142x550	x1	
2	2142x550	x1	
3	2142x200	x1	
4	2142x200	x1	
5	800x550	x1	
6	800x500	x1	
7	568x550	x1	
8	568x550	x1	
9	518x200	x1	
10	518x68	x1	
12	2171x297	x2	
13	1425x517	x1	
14	699x517	x1	
		x1	

№	a*b	x	№→...
11/1	2170x397	x1	
	 L-1000mm	x1	
15/2	2170x397	x1	
	 L-600mm	x1	


R



№	a*b	x	№→...
11/2	2170x397	x1	
	 L-600mm	x1	
15/1	2170x397	x1	
	 L-1000mm	x1	




 (C1) 6*43mm x4	 (D1) 15/16 x6	 (F4) 6,3*13mm x4
	 (L1) x2	 (L24) x2

1 L





 C1 6*43mm x12	 D1 15/16 x10
---	--





2 L





3 L






4 L+R




 (C1) 6*43mm x6	 (D1) 15/16 x16
--	--

5 L+R




 (E6) 3,5*16mm x8	 (L1) x2	 (L24) x2
--	--	--


6 L+R




7 L




8 L+R





9 L




10 L









11 L

 (K16) $\phi 50 \times h 27 \text{ mm}$ x4	 (O8) L-2141 mm x1
---	---







12 L











 E3 3*13mm x4	 P4 L-564mm x1	 P5 x2
--	---	---


13 L





14L









15 L




 (G5) M 4*20mm x6	 (I56) L-600 mm x1	 (I56) L-1000 mm x1
--	--	--


16 L







17 L


D	$\phi 20\text{mm}$	x55	U3	x2
---	--------------------	-----	----	----








1 R

 C1 6*43mm x4	 D1 15/16 x6	 F4 6,3*13mm x4
	 L1 x2	 L24 x2





 (C1) 6*43mm x12	 (D1) 15/16 x10
---	--


2 R




3 R




7 R





9 R




10 R






11R

 (K16) $\phi 50 \times h 27 \text{ mm}$ x4	 (O8) L-2141 mm x1
---	--







12 R











 E3 3*13mm x4	 P4 L-564mm x1	 P5 x2
--	---	---


13 R





14 R









15 R




 (G5) M 4*20mm x6	 (I56) L-600 mm x1	 (I56) L-1000 mm x1
--	--	--

16 R



17 R

 D $\phi 20\text{mm}$ x55	 U3 x2
---	---



18

