













Спейс / Space


**шафа з кутовим закінченням (2400) /
corner cabinet (2400)**









 (C1) 6*43mm x59	 (D) $\phi 20$ mm x59	 (D1) 15/15 x59
 (E3) 3*13mm x4	 (E6) 3,5*16mm x10	 (2E) 4,2*16mm x2
 (F4) 6,3*13mm x10	 (G5) M 4*20mm x6	 (K16) $\phi 50$ *h27mm x4
 (L1) x2	 (L24) x3	 (P4) L-564mm x1
 (P5) x2	 (O8) L-2341 mm x1	 (R3) 1.4*25mm 30g
 (S16) 260.54.900 x1	 (U3) x2	 (E15) 4*30mm x8


L

№	a*b	x	№→...
1	2342x550	x1	
2	2342x550	x1	
3	2342x200	x1	
4	2342x200	x1	
5	800x550	x1	
6	800x500	x1	
7	568x550	x1	
8	568x550	x1	
9	568x550	x1	
10	518x200	x1	
11	518x68	x1	
13	2371x297	x2	
14	1625x517	x1	
15	699x517	x1	
		x1	




№	a*b	x	№→...
12/1	2370x397	x1	
	 L-1000mm	x1	
16/2	2370x397	x1	
	 L-600mm	x1	

R


№	a*b	x	№→...
12/2	2370x397	x1	
	 L-600mm	x1	
16/1	2370x397	x1	
	 L-1000mm	x1	





STEP 4;5;6;8 - R/L


 (C1) 6*43mm x6	 (D1) 15/16 x6	 (F4) 6,3*13mm x4
	 (L1) x2	 (L24) x3

1 L





 (C1) 6*43mm x14	 (D1) 15/16 x11
---	--






2 L





3 L






4 L+R




 C1 6*43mm x6	 D1 15/16 x16
--	--

5 L+R




 E6 3,5*16mm x10	 L1 x2	 L24 x3
---	--	--


6 L+R




7 L




8 L+R




9 L



10 L




11 L



K16

φ50* h 27mm


x4





08


L-2341 mm

x1







12 L













 E3 3*13mm x4	 P4 L-564mm x1	 P5 x2
--	---	---

13 L




14 L




 G5 M 4*20mm x6	 I56 L-600 mm x1	 I56 L-1000 mm x1
--	--	--


16 L







17 L

D	Ø20mm	x59	U3	x2
---	-------	-----	----	----








STEP 4;5;6;8 - R/L


 C1 6*43mm x6	 D1 15/16 x6	 F4 6,3*13mm x4
	 L1 x2	 L24 x3

1 R





 C1 6*43mm x14	 D1 15/16 x11
---	--


2 R




3 R




7 R





9 R




10 R






11R

 (K16) $\phi 50 \times h 27 \text{ mm}$ x4	 (O8) L-2341 mm x1
---	--







12 R











 E3 3*13mm x4	 P4 L-564mm x1	 P5 x2
--	---	---


13R





14 R









15 R






 (G5) M 4*20mm x6	 (I56) L-600 mm x1	 (I56) L-1000 mm x1
--	--	--

16 R



17 R

 D $\phi 20\text{mm}$ x59	 U3 x2
---	---



18

