






A	B	C	D	
1	N100-127	1968	420	1/5
2	N100-128	1968	420	1/5
3	N100-910	1978	475	1/5
4	Lh-1962	1962	14	1/5
5	N100-015	196	934	2/5
6	N100-217	974	421	2/5
	N100-229			
7	N100-218	974	421	2/5
8	N100-311	941	400	2/5
9	N100-310	941	353	3/5
10	N100-312	941	353	3/5
11	N100-410	941	60	3/5
12	N100-501	350	120	3/5
13	N100-502	350	120	3/5
14	N100-515	883	120	3/5
15	N100-909	898	350	3/5
16	N100-016	1526	465	4/5
17	N100-419	941	60	3/5




4x c818	2x Ø6,3x15 mm d5	12x Ø3,5x15 mm p51	1x z1	22x l2	20x Ø15x12 mm #16 r1	20x r42	20x Ø8x30 mm f1
4x 350 mm w207/1	4x 350 mm w207/2	10x Ø7x50 mm e1	12x Ø3,5x12 mm p140	12x Ø6x13 mm e3	8x Ø5x50 mm e32	12x Ø5x17 mm d1	12x Ø16 s2
8x Ø3,5x13 mm p1	6x a27	6x b13	22x Ø3,5x16 mm p38	2x k129	1x n261/1	4x Ø3,5x16 mm p25	2x 333 mm t19



1






2




3



4



5



6

